



Equipment de travail à la Raffinerie

Standards in force at the Cressier Manufacturing Hub (Status at 01.01.2025)

The information presented is a minimum requirement and is not exhaustive. Additional protective equipment or alleviations may be required or authorized depending on the nature and location of the work, particularly during maintenance shutdowns.

<p>Helmet EN 397</p> <p>Safety glasses or over-glasses for medical correction glasses EN 166</p> <p>PPE against falling objects</p> <p>Overalls EN 531 (ISO 11612) <u>or</u> EN 533 (ISO 14116)</p> <p>Protective equipment for rain and cold weather (Besides the overall) EN 531 (ISO 11612) <u>or</u> EN 533 (ISO 14116) 14116)</p> <p>Safety shoes (Boot, metal shell, anti-perforation and anti-static sole) EN 345 / S3 ou S7</p>		<p>Inside unit limit, according to permit or local sign posting</p> <p>Hearing protector (hearplugs autorised) EN 352</p> <p>Detector : Minimum H2S / Or LEL</p> <p>Escape mask</p> <p> Orange jacket (Only on railroad) EN 471</p> <p>Working clothes and over-jackets must conform with norm EN 1149 (Propriétés électrostatiques)</p> <p>Working gloves EN388</p>
--	---	--